

[Open Peer Review on Qeios](#)

Unable to Position Lead Due to Coronary Sinus Dissection

National Cancer Institute

Source

National Cancer Institute. *Unable to Position Lead Due to Coronary Sinus Dissection*. NCI Thesaurus. Code C100028.

The coronary sinus / left ventricular lead was not implanted because the coronary sinus was dissected. (ACC)