

[Open Peer Review on Qeios](#)

Unable to Position Lead In tributary Vein of Coronary Sinus

National Cancer Institute

Source

National Cancer Institute. *Unable to Position Lead In tributary Vein of Coronary Sinus*.

NCI Thesaurus. Code C100029.

The coronary sinus / left ventricular lead was not implanted because the operator was unable to position the lead in the tributary vein of the coronary sinus. (ACC)