

[Open Peer Review on Qeios](#)

Unable to Obtain Satisfactory Coronary Sinus Access

National Cancer Institute

Source

National Cancer Institute. *Unable to Obtain Satisfactory Coronary Sinus Access*. NCI Thesaurus. Code C100026.

The coronary sinus / left ventricular lead was not implanted because the operator was unable to obtain satisfactory coronary sinus access. (ACC)