## Open Peer Review on Qeios

## Unable to Obtain Acceptable Pacing Thresholds

National Cancer Institute

## Source

National Cancer Institute. <u>Unable to Obtain Acceptable Pacing Thresholds</u>. NCI Thesaurus. Code C100025.

The coronary sinus / left ventricular lead was not implanted because the operator was unable to obtain acceptable pacing thresholds. (ACC)