

[Open Peer Review on Qeios](#)

Cardiac Pacemaker Undersensing

National Cancer Institute

Source

National Cancer Institute. *Cardiac Pacemaker Undersensing*. NCI Thesaurus. Code C99541.

Failure of pacemaker to detect appropriate cardiac depolarizations.