

[Open Peer Review on Qeios](#)

Cardiac Lead Position Results in Undesirable Stimulation of Diaphragm

National Cancer Institute

Source

National Cancer Institute. *Cardiac Lead Position Results in Undesirable Stimulation of Diaphragm*. NCI Thesaurus. Code C99933.

The coronary sinus / left ventricular lead was not implanted because the lead position resulted in undesirable stimulation of the diaphragm. (ACC)