

Open Peer Review on Qeios

Failure of Cardiac Pacemaker to Capture

National Cancer Institute

Source

National Cancer Institute. <u>Failure of Cardiac Pacemaker to Capture</u>. NCI Thesaurus. Code C99527.

Failure to capture manifests as a high pacing threshold that results in either intermittent failure to capture at maximal programmed output or excessive battery drain leading to premature battery exhaustion.

Qeios ID: B1SVYM · https://doi.org/10.32388/B1SVYM